

SQUBE 3.0ON 3 PHASE TRACK

20-Apr.-2019





DIMENSIONS





MOUNTING INSTRUCTION

- $oldsymbol{0}$ Make sure the knob is on the Loose position.
- 2 Push the fixture into the track.
- 3 Turn the knob to the Lock position. (Press the bolt and turn the knob at the same time)
- 4 Select the phase.

Dose position Lock position

Press the bolt and turn





The light source of the integrated LED is not replaceable; When the light source reaches its end of life the whole luminaire shall be replaced.

Caution, risk of electric shock

